

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

| | | | | | | | | | | | | | | |
|---|--|-----|------------|---|---------------------------|---------------------|-----------------------|-----------------------------|---|------------------|----------------|--------------------------------|------|--|
| Inspector's Name Jackson, Dave | | | | Inspector's Signature | | | | Inspector's ID No. M3003 | | Report No. 47 | | Date yy mm dd 2023 03 29 | | |
| Railroad/Company Name & Address BNSF RAILWAY COMPANY | | | | | | R/C R | Division SYSTEM | | RR/Co. Representative (Receipt Acknowledged) Name Matthew Krick Title Mechanical Foreman Email matthew.krick@bnsf.com Signature _____ | | | | | |
| | | | | | | RR/Co. Code BNSF | Subdivision SYSTEM | | | | | | | |
| | | | | | | | | | | | | | | |
| From: City ACTON | | | Codes 0004 | | Destination City & County | | | | Codes | | From Latitude | | | |
| State MT | | | 30 | | City | | | | | | From Longitude | | | |
| County YELLOWSTONE | | | C111 | | County | | | | | | To Latitude | | | |
| Mile Post: From To | | | | Inspection Point ACTON MAIN LINE SIDING | | | | | | To Longitude | | | | |
| Activity Code: | | 215 | 224 | 229D | 231 | 232 | 232X | | | | | | CARS | |
| Units: | | 140 | 140 | 4 | 144 | 140 | 1 | | | | | | 140 | |
| Sub Units: | | 0 | 0 | 0 | 0 | 0 | 1 | | | | | | 0 | |

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 1 | NCUX | 11746 | H | 215 | 0301 | A1 | | | ACTON MT | N | N | 1 | 215 |

Description
Left side car I.D. faded out to the point it is not fully readable.

| | | | | | | | |
|--------------|--|--------------|--|--------------|--|----------|--|
| Seal Applied | | Seal Removed | | Hazard Class | | UN/NA ID | |
| | | | | | | | |

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 2 | BNSF | 670414 | H | 215 | 0103 | A1 | | | ACTON MT | N | N | 1 | 215 |

Description
L-4 Wheel flange 2 FRA limits 7/8 inch.

| | | | | | | | |
|--------------|--|--------------|--|--------------|--|----------|--|
| Seal Applied | | Seal Removed | | Hazard Class | | UN/NA ID | |
| | | | | | | | |

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|-----------------------------|------------------|--------------------------|
| Inspector's ID No. M3003 | Report No. 47 | Report Date 3/29/2023 |
|-----------------------------|------------------|--------------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 3 | BNSF | 668666 | H | 215 | 0301 | A1 | | | ACTON MT | N | N | 1 | 215 |

Description

Left side car I.D. faded out to the point it is not readable.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 4 | BNSF | 668730 | H | 215 | 0301 | A1 | | | ACTON MT | N | N | 1 | 215 |

Description

Left side car I.D. faded out to the point it is not readable.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 5 | BNSF | 672027 | H | 215 | 0103 | A1 | | | ACTON MT | N | N | 1 | 215 |

Description

L-1 Wheel flange @ FRA limits 7/8 inch.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 6 | MQRX | 41903 | H | 232 | 0103 | F3 | | | ACTON MT | N | N | 1 | 232 |

Description

L-1 Brake shoe worn to the backing plate.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|-----------------------------|------------------|--------------------------|
| Inspector's ID No. M3003 | Report No. 47 | Report Date 3/29/2023 |
|-----------------------------|------------------|--------------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 7 | BN | 534205 | H | 215 | 0301 | A1 | | | ACTON MT | N | N | 1 | 215 |

Description

Left side build date missing.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 8 | BNSF | 669649 | H | 232 | 0103 | F3 | | | ACTON MT | N | N | 1 | 232 |

Description

L-4 Brake shoe worn to the backing plate.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 9 | BNSF | 668792 | H | 215 | 0117 | E1 | | | ACTON MT | N | N | 2 | 215 |

Description

R-1 & R-2 Roof liners are both shifted out of place.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 10 | BNSF | 668515 | H | 215 | 0301 | A1 | | | ACTON MT | N | N | 1 | 215 |

Description

Right side car I.D. faded out to the point it is not readable.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|-----------------------------|------------------|--------------------------|
| Inspector's ID No. M3003 | Report No. 47 | Report Date 3/29/2023 |
|-----------------------------|------------------|--------------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 11 | BNSF | 668515 | H | 215 | 0117 | E1 | | | ACTON MT | N | N | 1 | 215 |

Description

R-1 Roof liner damaged.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 12 | BNSF | 668518 | H | 215 | 0117 | E1 | | | ACTON MT | N | N | 1 | 215 |

Description

R-1 Roof liner shifted out of place.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 13 | BNSF | 671380 | H | | | | | | ACTON MT | N | N | 0 | |

Description - [** Comment to Railroad/Company **]

L-1 Wheel flange @ AAR limits 15/16 inch.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 14 | BNSF | 670607 | H | | | | | | ACTON MT | N | N | 0 | |

Description - [** Comment to Railroad/Company **]

R-1 Wheel flange @ AAR limits 15/16 inch.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|-----------------------------|------------------|--------------------------|
| Inspector's ID No. M3003 | Report No. 47 | Report Date 3/29/2023 |
|-----------------------------|------------------|--------------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 15 | BNSF | 671561 | H | | | | | | ACTON MT | N | N | 0 | |

Description - [** Comment to Railroad/Company **]

R-4 Wheel flange @ AAR limits 15/16 inch.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 16 | WFRX | 972925 | H | | | | | | ACTON MT | N | N | 0 | |

Description - [** Comment to Railroad/Company **]

R-1 Wheel has an AAR shell-out.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 17 | BNSF | 668518 | H | | | | | | ACTON MT | N | N | 0 | |

Description - [** Comment to Railroad/Company **]

A-R Spring nest has (1) broken spring within the nest.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|--------------|-------|-------|--------------|---------------|
| 18 | WFRX | 975321 | H | | | | | | ACTON MT | N | N | 0 | |

Description - [** Comment to Railroad/Company **]

A-R Spring nest has (1) broken spring within the nest.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|--------------------|------------|-------------|
| Inspector's ID No. | Report No. | Report Date |
| M3003 | 47 | 3/29/2023 |

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/ USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|----------------|--------|---------|-------|-------|--------------|-------|-------|-----------------|------------------|
| 19 | | | | 232 | | | | | ACTON MT | N | N | 0 | 232X |

Description - [** Comment to Railroad/Company **]

Inspected loaded coal train for securement of unattended equipment, no exceptions taken.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
| | | | |

| | | | | |
|-----------------------|------------------------------|--|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
| | | | | |

| | | | | | | | |
|---|-----------------------------------|--|----------------------|----------------------|-------------------|----------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required | <input checked="" type="checkbox"/> Optional | Railroad Action Code | <input type="text"/> | Date(mm/dd/yyyy): | <input type="text"/> | Comments on back? |
| | | | | | | | |