

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 68		Date yy mm dd 2023 08 31		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Great Falls MT						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name David Johnson Title Mechanical Foreman Email david.johnson122807@bnsf.com Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City GREAT FALLS			Codes 0530		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County CASCADE			C013		County						To Latitude			
Mile Post: From To				Inspection Point GREAT FALLS ROUNDHOUSE						To Longitude				
Activity Code:	229D	224	231	232X	LTM	218S								
Units:	13	13	13	1	1	3								
Sub Units:	0	0	0	3	3	0								

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	3965	EMF	229	0089	A1				N	N	1	229D

Description
Rear "MU" cable insecure/hanging with one end in hot receptacle.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	5909	EMF	229	0093	C1				N	N	1	229D

Description
(Left-side) emergency fuel cut off decal faded.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended ☐ Yes ☒ No Latitude: Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional Railroad Action Code Date(mm/dd/yyyy): Comments on back?

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3005	Report No. 68	Report Date 8/31/2023
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	7407	EMF	229	0059	E1				N	N	1	229D

Description
580 blowdown valve continuously leaking air.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	7407	EMF	232	0103	N8I				N	N	2	232X

Description
Inspected three locomotive consists for securement of unattended equipment, BNSF 7407 and BNSF 5962 isolation switches left in "run" position.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5										N	N	0	218S

Description - [** Comment to Railroad/Company **]
Observed three mechanical employees working on locomotives under proper blue signal protection, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------