

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 26		Date yy mm dd 2020 02 19		
Railroad/Company Name & Address MONTANA RAIL LINK 704 1/2 East Gallatin St P.O. Box 1380 Livingston MT 59047						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name William R Edwards Title Mechanical Foreman Email bedwards@mtrail.com Signature _____				
						RR/Co. Code MRL		Subdivision SYSTEM						
From: City LIVINGSTON				Codes 0750		Destination City & County				Codes		From Latitude		
State MT				30		City						From Longitude		
County PARK				C067		County						To Latitude		
Mile Post: From To				Inspection Point LIVINGSTON READY / FUEL TRACKS								To Longitude		
Activity Code:	224	229D	231	232X	232T									
Units:	6	6	6	2	2									
Sub Units:	0	0	0	0	0									
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
1	MRL	265	EMF	229	0119	C1			READY TRACK	N	N	1	229D	
Description TOOL ROOM FLOOR COVERED IN OIL.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
2	MRL	4404	EMF	229	0093	C1			READY TRACK	N	N	1	229D	
Description UNABLE TO FULLY READ RIGHT SIDE EMERGENCY FUEL SHUT OFF SIGNAGE.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?			

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 26	Report Date 2/19/2020
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	MRL	4405	EMF						READY TRACK	N	N	0	

Description - [** Comment to Railroad/Company **]

AIR LEAK @ UNION FITTING TO FRONT LEFT NUMBER 2 BRAKE CYLINDER. COMMENT ONLY LOCOMOTIVE DID PASS DAILY AIR TEST.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	MRL	4405	EMF						READY TRACK	N	N	0	

Description - [** Comment to Railroad/Company **]

REMOTE CONTROLLED UN-COUPLING DEVICE, LAST CALIBRATION WAS IN 2014. COMMENT ONLY.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5			EMF	232					READY TRACK	N	N	0	232X

Description - [** Comment to Railroad/Company **]

INSPECTED TWO LOCOMOTIVE CONSIST THAT HAD BEEN PREVIOUSLY WORKED / AIR TESTED FOR SECUREMENT OF UNATTENDED EQUIPMENT, NO EXCEPTIONS TAKEN.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------