

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name <b>Jackson, Dave</b>				Inspector's Signature				Inspector's ID No. <b>M3003</b>		Report No. <b>90</b>		Date		
												yy <b>2021</b>	mm <b>07</b>	dd <b>06</b>
Railroad/Company Name & Address <b>MONTANA RAIL LINK</b> <b>2800 Shannon Road</b>  <b>Laurel MT 59044</b>						R/C <b>R</b>		Division <b>SYSTEM</b>		RR/Co. Representative (Receipt Acknowledged)  Name <b>Mark Turner</b>  Title <b>General Mechanical Foreman</b>  Email <b>mturner@mtrail.com</b>  Signature _____				
						RR/Co. Code <b>MRL</b>		Subdivision <b>SYSTEM</b>						
From: City <b>LAUREL</b>				Codes <b>0700</b>		Destination City & County				Codes		From Latitude		
State <b>MT</b>				<b>30</b>		City						From Longitude		
County <b>YELLOWSTONE</b>				<b>C111</b>		County						To Latitude		
Mile Post: From				To		Inspection Point <b>LAUREL WEST TRACKS 1,2 &amp; 3</b>						To Longitude		
Activity Code:	<b>224</b>	<b>229D</b>	<b>231</b>	<b>232X</b>										
Units:	<b>10</b>	<b>10</b>	<b>10</b>	<b>3</b>										
Sub Units:	<b>0</b>	<b>0</b>	<b>0</b>	<b>1</b>										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
<b>1</b>	<b>BNSF</b>	<b>4649</b>	<b>EMF</b>	<b>229</b>	<b>0011</b>	<b>A1</b>			<b>LAUREL WEST</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>229D</b>	
Description <b>Right side letter "F" missing.</b>														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <input type="text"/> <input type="text"/> <input type="text"/>			Date(mm/dd/yyyy): <input type="text"/>		Comments on back?			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
<b>2</b>	<b>BNSF</b>	<b>9736</b>	<b>EMF</b>	<b>229</b>	<b>0045</b>	<b>C1</b>			<b>LAUREL WEST</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>229D</b>	
Description <b>Number 5 traction motor lead cables covered in oil.</b>														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <input type="text"/> <input type="text"/> <input type="text"/>			Date(mm/dd/yyyy): <input type="text"/>		Comments on back?			

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 90	Report Date 7/6/2021
-----------------------------	------------------	-------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	7263	EMF	231	0136	C2			LAUREL WEST	N	N	1	231

Description  
Right front side hand hold has 1 3/4 Inch of clearance.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	7263	EMF						LAUREL WEST	N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
L-6 Vertical shock has leaked out all of its hydraulic oil (dry now).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------