

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel		Inspector's Signature			Inspector's ID No. M3005		Report No. 2		Date yy mm dd 2025 01 09				
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Helena MT 59601				R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Kyle Patterson Title Mechanical Foreman Email kyle.patterson2@bnsf.com Signature _____						
				RR/Co. Code BNSF	Subdivision SYSTEM								
From: City HELENA		Codes 0590		Destination City & County			Codes		From Latitude				
State MT		30		City					From Longitude				
County LEWIS AND CLARK		C049		County					To Latitude				
Mile Post: From To				Inspection Point LTM				To Longitude					
Activity Code:	LTM												
Units:	1												
Sub Units:	1												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	LTM
Description - [** Comment to Railroad/Company **] Held safety briefing with BNSF manager discussing upcoming changes in staffing, internal processes and procedures. Blue signal protection and track protection changes were also discussed.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			