

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel			Inspector's Signature			Inspector's ID No. M3005		Report No. 12		Date yy mm dd 2024 02 01			
Railroad/Company Name & Address BNSF RAILWAY COMPANY Helena MT 59601						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Kyle Patterson Title Mechanical Foreman Email kyle.patterson2@bnsf.com Signature _____				
						RR/Co. Code BNSF	Subdivision SYSTEM						
From: City HELENA		Codes 0590		Destination City & County				Codes	From Latitude				
State MT		30		City					From Longitude				
County LEWIS AND CLARK		C049		County					To Latitude				
Mile Post: From To				Inspection Point HELENA ROUNDHOUSE					To Longitude				
Activity Code:	LTM												
Units:	1												
Sub Units:	3												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	LTM
Description - [** Comment to Railroad/Company **] Discussed new rule changes due to recent Montana Rail Link lease termination. Class I requirements, rules, regulations and policies were reviewed, as well as potential plans for locomotives/helper operations to be compliant with state and federal laws.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code			Date(mm/dd/yyyy):				Comments on back?	