

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 93		Date yy mm dd 2024 09 17		
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Laurel MT						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Assistant General Foreman Email harlan.penninger@bnsf.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City BOZEMAN			Codes 0130		Destination City & County				Codes	From Latitude				
State MT			30		City					From Longitude				
County GALLATIN			C031		County					To Latitude				
Mile Post: From To				Inspection Point BOZEMAN YARD						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	5	7	2	7	5	1							5	
Sub Units:	0	0	0	0	0	2							0	
Item 1	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code 232X	
Description - [** Comment to Railroad/Company **] Inspected one locomotive consist and one cut of cars for federal defects and securement of unattended equipment, no exceptions taken.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:						
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):					Comments on back?			