

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 50		Date yy mm dd 2022 04 05		
Railroad/Company Name & Address BNSF RAILWAY COMPANY						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matthew Krick Title Mechanical Foreman / Supervisor Email matthew.krick@bnsf.com gabriel.schlosser@bnsf.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City ACTON			Codes 0004		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point ACTON MAIN LINE SIDING						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	75	77	2	77	75	1							75	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	670427	H	231	0114	B2			ACTON	N	N	1	231

Description
Hand brake wheel bent, insufficient clearance.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:		Longitude:	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):	
						Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	669767	H	231	0114	B2			ACTON	N	N	1	231

Description
Hand brake wheel bent, insufficient clearance.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:		Longitude:	
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):	
						Comments on back?	

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 50	Report Date 4/5/2022
-----------------------------	------------------	-------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	668517	H	215	0301	A1			ACTON	N	N	1	215

Description
Left side car I.D. Number faded out, peeling & partly covered by reflective sheeting.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---------------------------------------------------------------------	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
----------------------------------------------------	--------------------------------------------------------------------------------	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	FURX	961798	H	215	0301	A1			ACTON	N	N	1	215

Description
Left side build date missing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---------------------------------------------------------------------	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
----------------------------------------------------	--------------------------------------------------------------------------------	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5				232					ACTON	N	N	0	232X

Description - [** Comment to Railroad/Company **]
Inspected N/B train set for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---------------------------------------------------------------------	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
----------------------------------------------------	--------------------------------------------------------------------------------	----------------------	-------------------	-------------------