

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel			Inspector's Signature			Inspector's ID No. M3005		Report No. 117		Date yy mm dd 2024 12 30			
Railroad/Company Name & Address BNSF RAILWAY COMPANY Missoula MT 59808					R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title Mechanical General Foreman Email matthew.olson@bnsf.com Signature _____					
					RR/Co. Code BNSF	Subdivision SYSTEM							
From: City MISSOULA		Codes 0830		Destination City & County				Codes	From Latitude				
State MT		30		City					From Longitude				
County MISSOULA		C063		County					To Latitude				
Mile Post: From To			Inspection Point MISSOULA						To Longitude				
Activity Code:	LTM												
Units:	1												
Sub Units:	1												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	LTM
Description - [** Comment to Railroad/Company **] Meeting with BNSF Mechanical Safety Manager - Discussion of upcoming safety changes for BNSF Mechanical Department in 2025. Blue signal protection, mechanical operating practices, internal management structure changes, etc,													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended			<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?	