

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 17		Date yy mm dd 2025 02 27		
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Helena MT 59601						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged)				
						RR/Co. Code BNSF		Subdivision SYSTEM		Name Kyle Patterson				
										Title Mechanical Foreman				
										Email kyle.patterson2@bnsf.com				
										Signature _____				

  

From: City HELENA		Codes 0590		Destination City & County				Codes		From Latitude			
State MT		30		City						From Longitude			
County LEWIS AND CLARK		C049		County						To Latitude			
Mile Post: From To				Inspection Point HELENA ROUNDHOUSE						To Longitude			
Activity Code:	224	229D	231	232X	218S	229X							
Units:	4	4	4	1	4	1							
Sub Units:	0	0	0	2	0	4							

  

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	MRL	4400	EMF	229	0067	A1				N	N	1	229D

Description  
(L3) vertical shock leaking oil.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

  

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	MRL	4400	EMF	229	0045	B5				N	N	0	229D

Description - [\*\* Comment to Railroad/Company \*\*]  
(L3) wheel bearing purging grease.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No      Latitude:      Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional      Railroad Action Code      Date(mm/dd/yyyy):      Comments on back?

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3005	Report No. 17	Report Date 2/27/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3										N	N	0	218S

Description - [\*\* Comment to Railroad/Company \*\*]

Observed mechanical employees servicing locomotives under blue signal protection on other than main track, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4										N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected two locomotive consists for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------