

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 88		Date yy mm dd 2022 06 14		
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1135 1st Street  Havre MT 59501						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Jack Murray Title General Foreman Email jack.murray2@bnsf.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City GLASGOW			Codes 0490		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County VALLEY			C105		County						To Latitude			
Mile Post: From To				Inspection Point GLASGOW EAST RAIL YARD						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	40	42	2	42	40	1							40	
Sub Units:	0	0	0	0	0	1							0	
Item 1	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site GLASGOW EAST	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code	
Description - [** Comment to Railroad/Company **] Inspected one train set for CFR parts 215, 224, 229, 231 & 232 no exceptions or defects found.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:			Longitude:							
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code			Date(mm/dd/yyyy):			Comments on back?				