

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 105		Date yy mm dd 2023 07 20		
Railroad/Company Name & Address BNSF RAILWAY COMPANY 1135 1st Street Havre MT 59501						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Jack Murray Title General Foreman Email jack.murray2@bnsf.com Signature _____					
						RR/Co. Code BNSF	Subdivision SYSTEM							
From: City GLASGOW			Codes 0490		Destination City & County				Codes	From Latitude				
State MT			30		City					From Longitude				
County VALLEY			C105		County					To Latitude				
Mile Post: From			To		Inspection Point GLASGOW (EAST) RAIL YARD					To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	25	28	3	28	25	1							25	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	4736	EMF	229	0045	A4			GLASGOW EAST	N	N	1	229D
Description Right front M.U. valve leaking air.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	4736	EMF	229	0067	A1			GLASGOW EAST	N	N	1	229D
Description L-6 Vertical shock leaking hydraulic oil.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code			Date(mm/dd/yyyy):		Comments on back?		

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No.	Report No.	Report Date
M3003	105	7/20/2023

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3				232					GLASGOW EAST	N	N	0	232X

Description - [** Comment to Railroad/Company **]

Inspected W/B train for securement of unattended equipment, no exceptions taken.

*Note was not able to inspect last 60 cars due to unsafe walking conditions.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	----------------------------------------	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
-------------------------------------------------------	-----------------------------------	----------------------------------------------	----------------------	----------------------	-------------------	----------------------	-------------------