

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave		Inspector's Signature			Inspector's ID No. M3003		Report No. 130		Date yy mm dd 2023 08 28				
Railroad/Company Name & Address BNSF RAILWAY COMPANY Great Falls MT				R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name David Johnson Title Mechanical Foreman Email david.johnson122807@bnsf.com Signature _____						
				RR/Co. Code BNSF	Subdivision SYSTEM								
From: City ACTON		Codes 0004		Destination City & County			Codes		From Latitude				
State MT		30		City					From Longitude				
County YELLOWSTONE		C111		County					To Latitude				
Mile Post: From To				Inspection Point ACTON MONTANA				To Longitude					
Activity Code:	229D												
Units:	2												
Sub Units:	0												
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	8758	EMF	229	0125	A2			ACTON MT	N	N	1	229D
Description Locomotive dual headlights are non-op, this is the controlling unit.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:			Longitude:						
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code			Date(mm/dd/yyyy):				Comments on back?		