

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

| | | | | | | | | | | | | | | |
|---|-------------------|-------------------|-------------------|---|---------------------------|---|-------|------------------------------------|--|--|-------------------|-------------------|-----------------|-----------------|
| Inspector's Name Jackson, Dave | | | | Inspector's Signature | | | | Inspector's ID No. M3003 | | Report No. 17 | | Date | | |
| | | | | | | | | | | | | yy 2024 | mm 01 | dd 30 |
| Railroad/Company Name & Address BNSF RAILWAY COMPANY 2800 Shannon Road Laurel MT 59044 | | | | | | R/C R | | Division SYSTEM | | RR/Co. Representative (Receipt Acknowledged) Name Mark Turner Title General Mechanical Foreman Email Signature _____ | | | | |
| | | | | | | RR/Co. Code BNSF | | Subdivision SYSTEM | | | | | | |
| | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | |
| From: City LAUREL | | | Codes 0700 | | Destination City & County | | | | Codes | | From Latitude | | | |
| State MT | | | 30 | | City | | | | | | From Longitude | | | |
| County YELLOWSTONE | | | C111 | | County | | | | | | To Latitude | | | |
| Mile Post: From To | | | | Inspection Point LAUREL WEST TRACK 3 | | | | | | To Longitude | | | | |
| Activity Code: | 224 | 229D | 231 | 232X | | | | | | | | | | |
| Units: | 3 | 3 | 3 | 1 | | | | | | | | | | |
| Sub Units: | 0 | 0 | 0 | 1 | | | | | | | | | | |
| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/ USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code | |
| 1 | BNSF | 5163 | EMF | 229 | 0045 | C1 | | | LAUREL WEST T3 | N | N | 1 | 229D | |
| Description Rear main seal leaking oil onto main generator. | | | | | | | | | | | | | | |
| Seal Applied | | | Seal Removed | | | Hazard Class | | | UN/NA ID | | | | | |
| Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | | | | Latitude: | | | Longitude: | | | | | |
| Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | | | | | | Railroad Action Code <input type="text"/> <input type="text"/> <input type="text"/> | | | Date(mm/dd/yyyy): <input type="text"/> | | Comments on back? | | | |
| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/ USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code | |
| 2 | BNSF | 5697 | EMF | 229 | 0045 | C1 | | | LAUREL WEST T3 | N | N | 1 | 229D | |
| Description Rear main seal leaking oil onto main generator. | | | | | | | | | | | | | | |
| Seal Applied | | | Seal Removed | | | Hazard Class | | | UN/NA ID | | | | | |
| Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | | | | | | Latitude: | | | Longitude: | | | | | |
| Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | | | | | | Railroad Action Code <input type="text"/> <input type="text"/> <input type="text"/> | | | Date(mm/dd/yyyy): <input type="text"/> | | Comments on back? | | | |

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|-----------------------------|------------------|--------------------------|
| Inspector's ID No. M3003 | Report No. 17 | Report Date 1/30/2024 |
|-----------------------------|------------------|--------------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|-------------------|-------|-------|--------------|---------------|
| 3 | BNSF | 5697 | EMF | 229 | 0067 | A1 | | | LAUREL WEST T3 | N | N | 2 | 229D |

Description

L-4 & L-6 Vertical shocks leaking hydraulic oil.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|-------------------|-------|-------|--------------|---------------|
| 4 | BNSF | 5697 | EMF | 229 | 0045 | A4 | | | LAUREL WEST T3 | N | N | 1 | 229D |

Description

Right rear external air dryer, continuously exhausting air.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|-------------------|-------|-------|--------------|---------------|
| 5 | BNSF | 8235 | EMF | 229 | 0045 | A4 | | | LAUREL WEST T3 | N | N | 1 | 229D |

Description

Radiator leaking coolant.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|------------|--------|---------|-------|-------|-------------------|-------|-------|--------------|---------------|
| 6 | BNSF | 8235 | EMF | 229 | 0067 | A1 | | | LAUREL WEST T3 | N | N | 3 | 229D |

Description

R-1, R-3 & L-4 Vertical shocks leaking hydraulic oil.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
|--------------|--------------|--------------|----------|

| | | | |
|-----------------------|---|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|---|-----------|------------|

| | | | | |
|--|--|----------------------|-------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional | Railroad Action Code | Date(mm/dd/yyyy): | Comments on back? |
|--|--|----------------------|-------------------|-------------------|

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

| | | |
|--------------------|------------|-------------|
| Inspector's ID No. | Report No. | Report Date |
| M3003 | 17 | 1/30/2024 |

| Item | Initials/Milepost | Equipment/Track # | Type/Kind | 49 CFR/ USC | Defect | Subrule | Speed | Class | Train #/Site | SNFR* | RCL** | # of Occ.*** | Activity Code |
|------|-------------------|-------------------|-----------|----------------|--------|---------|-------|-------|-------------------|-------|-------|-----------------|------------------|
| 7 | | | | 232 | | | | | LAUREL WEST T3 | N | N | 0 | 232X |

Description - [** Comment to Railroad/Company **]

Inspected (1) Locomotive consist for securement of unattended equipment, no exceptions taken.

| | | | |
|--------------|--------------|--------------|----------|
| Seal Applied | Seal Removed | Hazard Class | UN/NA ID |
| | | | |

| | | | | |
|-----------------------|------------------------------|--|-----------|------------|
| Violation Recommended | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No | Latitude: | Longitude: |
|-----------------------|------------------------------|--|-----------|------------|

| | | | | | | | |
|---|-----------------------------------|--|----------------------|----------------------|-------------------|----------------------|-------------------|
| Written Notification to FRA of Remedial Action is: | <input type="checkbox"/> Required | <input checked="" type="checkbox"/> Optional | Railroad Action Code | <input type="text"/> | Date(mm/dd/yyyy): | <input type="text"/> | Comments on back? |
|---|-----------------------------------|--|----------------------|----------------------|-------------------|----------------------|-------------------|