

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 58		Date yy mm dd 2024 04 10		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger				
						RR/Co. Code BNSF		Subdivision SYSTEM		Title Car Shop / Road Truck Foreman				
						Email								
						Signature _____								
From: City FORSYTH			Codes 0430		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County ROSEBUD			C087		County						To Latitude			
Mile Post: From To				Inspection Point FORSYTH YARD (ALL POINTS)							To Longitude			
Activity Code:		215	224	229D	231	232	232X						CARS	
Units:		22	23	1	23	22	5						22	
Sub Units:		0	0	0	0	0	1						0	
Item 1	Initials/Milepost BNSF	Equipment/Track # 7971	Type/Kind EMF	49 CFR/USC 229	Defect 0119	Subrule E1	Speed	Class	Train #/Site FORSYTH YARD	SNFR* N	RCL** N	# of Occ.*** 1	Activity Code 229D	
Description Rear continuous barrier not in place.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?						
Item 2	Initials/Milepost BNSF	Equipment/Track # 7971	Type/Kind EMF	49 CFR/USC 229	Defect 0067	Subrule A1	Speed	Class	Train #/Site FORSYTH YARD	SNFR* N	RCL** N	# of Occ.*** 1	Activity Code 229D	
Description R-1 Vertical shock leaking hydraulic oil.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?						

Source Code A	File Number	ID's of Accompanying Inspector(s)
------------------	-------------	-----------------------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT
(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 58	Report Date 4/10/2024
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	7971	EMF	229	0119	C1			FORSYTH YARD	N	N	1	229D

Description
Fuel leaking onto right walkway.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/> <input type="text"/> <input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	--	----------------------	--	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	7971	EMF	229	0045	C1			FORSYTH YARD	N	N	1	229D

Description
Air compressor bypassing oil onto electric drive motor.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/> <input type="text"/> <input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	--	----------------------	--	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	ITFX	7428	H	215	0301	A1			FORSYTH YARD	N	N	1	215

Description
Left side bulid date missing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/> <input type="text"/> <input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	--	----------------------	--	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6				232					FORSYTH YARD	N	N	0	

Description - [** Comment to Railroad/Company **]
Inspected (1) locomotive & (4) cuts of rail cars for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/> <input type="text"/> <input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	--	----------------------	--	-------------------	----------------------	-------------------

Source Code A	File Number	ID's of Accompanying Inspector(s)
------------------	-------------	--------------------------------------