

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name <b>Jackson, Dave</b>				Inspector's Signature				Inspector's ID No. <b>M3003</b>		Report No. <b>129</b>		Date		
												yy <b>2024</b>	mm <b>07</b>	dd <b>29</b>
Railroad/Company Name & Address <b>BNSF RAILWAY COMPANY</b>  <b>Laurel MT</b>						R/C <b>R</b>		Division <b>SYSTEM</b>		RR/Co. Representative (Receipt Acknowledged) Name <b>Harlan Penninger</b> Title <b>Car Shop / Road Truck Foreman</b> Email Signature _____				
						RR/Co. Code <b>BNSF</b>		Subdivision <b>SYSTEM</b>						
From: City <b>ACTON</b>			Codes <b>0004</b>		Destination City & County				Codes		From Latitude			
State <b>MT</b>			<b>30</b>		City						From Longitude			
County <b>YELLOWSTONE</b>			<b>C111</b>		County						To Latitude			
Mile Post: From To				Inspection Point <b>ACTON MAIN LINE SIDING</b>						To Longitude				
Activity Code:	<b>215</b>	<b>224</b>	<b>229D</b>	<b>231</b>	<b>232</b>	<b>232X</b>						<b>CARS</b>		
Units:	<b>10</b>	<b>13</b>	<b>3</b>	<b>13</b>	<b>10</b>	<b>1</b>						<b>10</b>		
Sub Units:	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>1</b>						<b>0</b>		

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
<b>1</b>	<b>BNSF</b>	<b>6162</b>	<b>EMF</b>	<b>229</b>	<b>0119</b>	<b>C1</b>			<b>ACTON MT</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>229D</b>

Description  
 Fuel / Oil mix on both left & right sides walkways.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
<b>2</b>	<b>BNSF</b>	<b>8108</b>	<b>EMF</b>	<b>229</b>	<b>0045</b>	<b>A4</b>			<b>ACTON MT</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>229D</b>

Description  
 Protective cover disconnected, laying on floor of air compressor room.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

**DEPARTMENT OF TRANSPORTATION**  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 129	Report Date 7/29/2024
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	8108	EMF	229	0067	A1			ACTON MT	N	N	1	229D

Description  
L-4 Vertical shock leaking hydraulic oil.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	CBTX	787459	T						ACTON MT	N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
Top tank car lid open.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5				232					ACTON MT	N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]  
Inspected (3) Locomotives & (10) Rail cars for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------