

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 220		Date		
												yy 2024	mm 12	dd 19
Railroad/Company Name & Address BNSF RAILWAY COMPANY Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Car Shop / Road Truck Foreman Email Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City BILLINGS				Codes 0100		Destination City & County				Codes		From Latitude		
State MT				30		City						From Longitude		
County YELLOWSTONE				C111		County						To Latitude		
Mile Post: From To				Inspection Point BILLINGS YARD								To Longitude		
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	100	102	2	102	100	4							100	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	2705	EMF	229	0045	C1			BILLINGS YARD	N	N	1	229D

Description
 Number (3) traction motor cables covered in oil.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No

Latitude:

Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional

Railroad Action Code

Date(mm/dd/yyyy):

Comments on back?

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	GATX	57199	T	231	0138	A11			BILLINGS YARD	N	N	1	231

Description
 Top continuous barrier not in place.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	

Violation Recommended ☐ Yes ☒ No

Latitude:

Longitude:

Written Notification to FRA of Remedial Action is: ☐ Required ☒ Optional

Railroad Action Code

Date(mm/dd/yyyy):

Comments on back?

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 220	Report Date 12/19/2024
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	GATX	75287	T	231	0138	A11			BILLINGS YARD	N	N	1	231

Description
Top continuous barrier not in place.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	UTLX	955148	T	232	0103	F3			BILLINGS YARD	N	N	1	232

Description
R-3 Brake shoe broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	GACX	13998	H	224	0103	C			BILLINGS YARD	N	N	1	224

Description
Right side retroreflective sheeting damaged / burned.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	BNSF	451562	H	224	0103	C			BILLINGS YARD	N	N	1	224

Description
Left side retroreflective sheeting painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 220	Report Date 12/19/2024
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	BNSF	403245	H	224	0103	C			BILLINGS YARD	N	N	1	224

Description

Right side retroreflective sheeting painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	BNSF	403245	H	215	0301	A1			BILLINGS YARD	N	N	2	215

Description

Right side car I.D. & Build date painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	GACX	13998	H						BILLINGS YARD	N	N	0	

Description - [Comment to Railroad/Company **]**

Right side AEI tag damaged / burned.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	GABX	690	H						BILLINGS YARD	N	N	0	

Description - [Comment to Railroad/Company **]**

A-L Spring nest has (1) coil spring shifted outside the nest, not fully supporting load.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No.	Report No.	Report Date
M3003	220	12/19/2024

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11				232					BILLINGS YARD	N	N	0	232X

Description - [** Comment to Railroad/Company **]

Inspected (4) cuts of rail cars for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	------------------------------	--	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
---	-----------------------------------	--	----------------------	----------------------	-------------------	----------------------	-------------------