

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 75		Date		
												yy 2025	mm 04	dd 29
Railroad/Company Name & Address BNSF RAILWAY COMPANY Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Harlan Penninger Title Car Shop / Road Truck Foreman Email Signature _____				
						RR/Co. Code BNSF		Subdivision SYSTEM						
From: City BOZEMAN				Codes 0130		Destination City & County				Codes		From Latitude		
State MT				30		City						From Longitude		
County GALLATIN				C031		County						To Latitude		
Mile Post: From To				Inspection Point BOZEMAN RAIL YARD (ALL POINTS)								To Longitude		
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	80	82	2	82	80	5							80	
Sub Units:	0	0	0	0	0	1							0	
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
1	MRL	110010	H	215	0301	A1			BOZEMAN YARD	N	N	1	215	
Description Left side build date painted over.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <input type="text"/> <input type="text"/> <input type="text"/>			Date(mm/dd/yyyy): <input type="text"/>		Comments on back?			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
2	CTCX	731672	T	231	0110	B1			BOZEMAN YARD	N	N	1	231	
Description Hand brake stuck in the released position.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <input type="text"/> <input type="text"/> <input type="text"/>			Date(mm/dd/yyyy): <input type="text"/>		Comments on back?			

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 75	Report Date 4/29/2025
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	MRL	51019	CH						BOZEMAN YARD	N	N	0	

Description - [** Comment to Railroad/Company **]

#1 Bottom hopper door open.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	MRL	42050	G						BOZEMAN YARD	N	N	0	

Description - [** Comment to Railroad/Company **]

Right side "AEI" tag broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	MRL	40004	G						BOZEMAN YARD	N	N	0	

Description - [** Comment to Railroad/Company **]

Right side "AEI" tag broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6				232					BOZEMAN YARD	N	N	0	232X

Description - [** Comment to Railroad/Company **]

Inspected (1) Locomotive consist & (4) cuts of rail cars for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------