

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 86		Date yy mm dd 2025 06 02		
Railroad/Company Name & Address BNSF RAILWAY COMPANY Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged)				
						RR/Co. Code BNSF		Subdivision SYSTEM		Name Harlan Penninger				
						Title Car Shop / Road Truck Foreman								
						Email								
Signature														
From: City LAUREL			Codes 0700		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point LAUREL WEST TRACK-1						To Longitude				
Activity Code:	215	224	229D	231	232	232X							CARS	
Units:	110	114	4	114	110	1							110	
Sub Units:	0	0	0	0	0	1							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	6907	EMF	229	0045	A4			LAUREL WEST T1	N	N	1	229D
Description Mechanical faster missing for the #1 traction motor cables (on top of the traction motor).													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	7371	EMF	229	0119	C1			LAUREL WEST T1	N	N	1	229D
Description Oil on Left / Rear walkway (next to hand brake).													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?	

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 86	Report Date 6/2/2025
-----------------------------	------------------	-------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	9079	EMF	229	0067	A1			LAUREL WEST T1	N	N	1	229D

Description

L-4 Vertical shock leaking hydraulic oil.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	9079	EMF	229	0045	A4			LAUREL WEST T1	N	N	1	229D

Description

L-2 Brake cylinder leaking air @ union fitting.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	BNSF	672481	H	232	0103	F3			LAUREL WEST T1	N	N	1	232

Description

L-2 Brake shoe worn to the backing plate.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	BN	534947	H	215	0301	A1			LAUREL WEST T1	N	N	1	215

Description

Right side build date painted over.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?
--	--	----------------------	----------------------	-------------------	----------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 86	Report Date 6/2/2025
-----------------------------	------------------	-------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	BNSF	669335	H	232	0103	F3			LAUREL WEST T1	N	N	1	232

Description

R-3 Brake shoe worn to the backing plate.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	BNSF	666262	H	215	0117	E1			LAUREL WEST T1	N	N	1	215

Description

R-1 & R-2 Roof liners are shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	BN	535040	H	215	0117	E1			LAUREL WEST T1	N	N	1	215

Description

R-2 Roof liner are shifted / damaged.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	BNSF	669029	H	215	0119	D3I			LAUREL WEST T1	N	N	1	215

Description

B-R Spring nest missing (2) coil springs.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 86	Report Date 6/2/2025
-----------------------------	------------------	-------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	WFRX	972876	H	215	0119	D3I			LAUREL WEST TJ	N	N	1	215

Description

B-R Spring nest has (2) coil spring shifted (not fully supporting load).

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
12	BN	535644	H	232	0103	F3			LAUREL WEST TJ	N	N	1	232

Description

R-3 Brake shoe worn to the backing plate.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
13	BNSF	669931	H						LAUREL WEST TJ	N	N	0	

Description - [Comment to Railroad/Company **]**

A-R Spring nest has (1) shifted coil spring within the nest.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
14	CEFX	41526	H						LAUREL WEST TJ	N	N	0	

Description - [Comment to Railroad/Company **]**

B-R Spring nest has (1) broken coil spring.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No.	Report No.	Report Date
M3003	86	6/2/2025

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
15				232					LAUREL WEST T1	N	N	0	232X

Description - [** Comment to Railroad/Company **]

Inspected W/B Coal fleet for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID

Violation Recommended	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	Latitude:	Longitude:

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required	<input checked="" type="checkbox"/> Optional	Railroad Action Code	<input type="text"/>	Date(mm/dd/yyyy):	<input type="text"/>	Comments on back?