

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name <b>Jackson, Dave</b>				Inspector's Signature				Inspector's ID No. <b>M3003</b>		Report No. <b>177</b>		Date		
												yy <b>2025</b>	mm <b>12</b>	dd <b>09</b>
Railroad/Company Name & Address <b>BNSF RAILWAY COMPANY</b>  <b>Laurel MT 59044</b>						R/C <b>R</b>		Division <b>SYSTEM</b>		RR/Co. Representative (Receipt Acknowledged) Name <b>Harlan Penninger</b> Title <b>Car Shop / Road Truck Foreman</b> Email Signature _____				
						RR/Co. Code <b>BNSF</b>		Subdivision <b>SYSTEM</b>						
From: City <b>LAUREL</b>			Codes <b>0700</b>		Destination City & County				Codes		From Latitude			
State <b>MT</b>			<b>30</b>		City						From Longitude			
County <b>YELLOWSTONE</b>			<b>C111</b>		County						To Latitude			
Mile Post: From				To		Inspection Point <b>LAUREL LOCOMOTIVE ROUND HOUSE (WHEEL TRACK)</b>				To Longitude				
Activity Code:	<b>229D</b>	<b>231</b>	<b>232X</b>											
Units:	<b>1</b>	<b>1</b>	<b>1</b>											
Sub Units:	<b>0</b>	<b>0</b>	<b>1</b>											
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
<b>1</b>	<b>MRL</b>	<b>265</b>	<b>EMF</b>						<b>LAUREL ROUND HO</b>	<b>N</b>	<b>N</b>	<b>0</b>		
Description - [** Comment to Railroad/Company **] Inspected MRL-265 for (One Time Movement) from post accident. Unit had been derailed on to its left side with damage to front / rear steps & fuel tank ripped open. The Fuel has been pumped out / emptied. Safety appliances have marked with contrasting paint & lettering. Electrical panel "Knife Switch" is disconnected with main fuse also removed. Locomotive is marked with "Do Not Occupy" on all entry points & control stand. No exceptions taken to condition for OTM to Livingston Montana locomotive repair shop.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code	
<b>2</b>				<b>232</b>					<b>LAUREL ROUND HO</b>	<b>N</b>	<b>N</b>	<b>0</b>	<b>232X</b>	
Description - [** Comment to Railroad/Company **] Inspected (1) locomotive for securement of unattended equipment, no exceptions taken.														
Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			