

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Jackson, Dave				Inspector's Signature				Inspector's ID No. M3003		Report No. 176		Date yy mm dd 2025 12 09		
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Laurel MT 59044						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged)				
						RR/Co. Code BNSF		Subdivision SYSTEM		Name Harlan Penninger				
						Title Car Shop / Road Truck Foreman								
						Email								
Signature														
From: City LAUREL			Codes 0700		Destination City & County				Codes		From Latitude			
State MT			30		City						From Longitude			
County YELLOWSTONE			C111		County						To Latitude			
Mile Post: From To				Inspection Point LAUREL WEST TRACK-3						To Longitude				
Activity Code:	224	229D	231	232X										
Units:	4	4	4	1										
Sub Units:	0	0	0	1										

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	5425	EMF	229	0011	A1			LAUREL WEST T3	N	N	1	229D
Description Right front letter "F" missing.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	BNSF	5425	EMF	229	0045	C1			LAUREL WEST T3	N	N	1	229D
Description Oil on generator.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?	

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 176	Report Date 12/9/2025
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	BNSF	5425	EMF	229	0119	C1			LAUREL WEST T3	N	N	1	229D

Description  
Oil on left side walkway.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	BNSF	5425	EMF	229	0067	A1			LAUREL WEST T3	N	N	1	229D

Description  
Rear inner horizontal shock leaking hydraulic oil.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	BNSF	8425	EMF	229	0119	C1			LAUREL WEST T3	N	N	1	229D

Description  
Oil on both left & right walkways.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	BNSF	5665	EMF	229	0045	C1			LAUREL WEST T3	N	N	1	229D

Description  
Oil on generator.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

**DEPARTMENT OF TRANSPORTATION**  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 176	Report Date 12/9/2025
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	BNSF	5665	EMF	229	0045	C1			LAUREL WEST T3	N	N	1	229D

Description

Oil on air compressor electric drive motor.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	BNSF	6619	EMF	229	0045	C1			LAUREL WEST T3	N	N	1	229D

Description

Oil on air compressor electric drive motor.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	BNSF	6619	EMF	229	0119	C1			LAUREL WEST T3	N	N	1	229D

Description

Oil on left / rear walkway.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10				232					LAUREL WEST T3	N	N	0	232X

Description - [\*\* Comment to Railroad/Company \*\*]

Inspected locomotive consist for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------