

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 28		Date yy mm dd 2024 03 25			
Railroad/Company Name & Address BNSF RAILWAY COMPANY Great Falls MT						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name David Johnson Title Mechanical Foreman Email david.johnson122807@bnsf.com Signature _____					
						RR/Co. Code BNSF		Subdivision SYSTEM							
From: City BUTTE			Codes 0180		Destination City & County				Codes		From Latitude				
State MT			30		City						From Longitude				
County SILVER BOW			C093		County						To Latitude				
Mile Post: From To				Inspection Point BUTTE YARD								To Longitude			
Activity Code:		215	224	229D	231	232	232X							CARS	
Units:		37	39	2	39	39	1							37	
Sub Units:		0	0	0	0	0	3							0	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	BNSF	162	EMF	229	0061	A3				N	N	2	229D

Description
(Front and rear couplers) have insufficient anti-creep protection.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	GATX	229983	T	232	0103	F3				N	N	1	232

Description
(L2) brake shoe worn to backing plate.

Seal Applied		Seal Removed		Hazard Class		UN/NA ID	
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:		Longitude:			
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?	

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3005	Report No. 28	Report Date 3/25/2024
-----------------------------	------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	NATX	302752	T	231	0130	A3				N	N	1	231

Description
(BR) sill step loose.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	NATX	302752	T	231	0031	A1				N	N	1	231

Description
(A-end) drawbar height less than 31 1/2" from top of rail.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	TILX	732292	T	232	0103	F3				N	N	1	232

Description
(R4) brake shoe worn to backing plate.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6										N	N	0	232X

Description - [** Comment to Railroad/Company **]
Inspected two cuts of cars and one locomotive consist for securement of unattended equipment, no exceptions taken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------