

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel		Inspector's Signature			Inspector's ID No. M3005		Report No. 59		Date yy mm dd 2025 06 25				
Railroad/Company Name & Address BNSF RAILWAY COMPANY Helena MT 59601					R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Kyle Patterson Title Mechanical Foreman Email kyle.patterson2@bnsf.com Signature _____					
					RR/Co. Code BNSF	Subdivision SYSTEM							
From: City MONTANA CITY		Codes 0841		Destination City & County				Codes		From Latitude			
State MT		30		City						From Longitude			
County JEFFERSON		C043		County						To Latitude			
Mile Post: From To				Inspection Point MONTANA CITY SIDING					To Longitude				
Activity Code:	224	229D	231	232X	LTM								
Units:	2	2	2	1	1								
Sub Units:	0	0	0	2	4								
Item 1	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR* N	RCL** N	# of Occ.*** 0	Activity Code 229D
Description - [** Comment to Railroad/Company **] Inspected one locomotive consist for federal defects and securement of unattended equipment, no exceptions taken.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					Latitude:				Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional					Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?		