

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Sherwood, Daniel				Inspector's Signature				Inspector's ID No. M3005		Report No. 69		Date yy mm dd 2025 07 23	
Railroad/Company Name & Address BNSF RAILWAY COMPANY  Missoula MT 59808						R/C R	Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title Mechanical General Foreman Email matthew.olson@bnsf.com Signature _____				
						RR/Co. Code BNSF	Subdivision SYSTEM						
From: City BUTTE			Codes 0180		Destination City & County				Codes	From Latitude			
State MT			30		City					From Longitude			
County SILVER BOW			C093		County					To Latitude			
Mile Post: From			To		Inspection Point BUTTE YARD					To Longitude			
Activity Code:	215	224	229D	231	232	232X						CARS	
Units:	11	12	1	12	11	1						11	
Sub Units:	0	0	0	0	0	3						0	
Item 1	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code 232X
Description - [** Comment to Railroad/Company **] Inspected one locomotive and two cuts of cars for federal defects under 49 CFR parts 215, 224, 229, 231 and 232, no exceptions taken. Inspected one locomotive and two cuts of cars for securement of unattended equipment, no exceptions taken.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			