

DEPARTMENT OF TRANSPORTATION  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name <b>Jackson, Dave</b>				Inspector's Signature				Inspector's ID No. <b>M3003</b>		Report No. <b>127</b>		Date		
												yy <b>2023</b>	mm <b>08</b>	dd <b>22</b>
Railroad/Company Name & Address <b>MONTANA RAIL LINK</b> <b>2800 Shannon Road</b>  <b>Laurel MT 59044</b>						R/C <b>R</b>		Division <b>SYSTEM</b>		RR/Co. Representative (Receipt Acknowledged)  Name <b>Mark Turner</b>  Title <b>General Mechanical Foreman</b>  Email <b>mturner@mtrail.com</b>  Signature _____				
						RR/Co. Code <b>MRL</b>		Subdivision <b>SYSTEM</b>						
From: City <b>LAUREL</b>				Codes <b>0700</b>		Destination City & County				Codes		From Latitude		
State <b>MT</b>				<b>30</b>		City						From Longitude		
County <b>YELLOWSTONE</b>				<b>C111</b>		County						To Latitude		
Mile Post: From To				Inspection Point <b>LAUREL WEST TRACK-3</b>								To Longitude		
Activity Code:	<b>215</b>	<b>224</b>	<b>229D</b>	<b>231</b>	<b>232</b>	<b>LTM</b>						<b>CARS</b>		
Units:	<b>75</b>	<b>78</b>	<b>3</b>	<b>78</b>	<b>75</b>	<b>2</b>						<b>75</b>		
Sub Units:	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>1</b>						<b>0</b>		

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
<b>1</b>	<b>BNSF</b>	<b>6191</b>	<b>EMF</b>	<b>229</b>	<b>0045</b>	<b>B1</b>			<b>LAUREL WEST T3</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>229D</b>
Description <b>Left side fuel cap disconnected.</b>													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <div style="border: 1px solid black; width: 20px; height: 20px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; display: inline-block;"></div>			Date(mm/dd/yyyy): <div style="border: 1px solid black; width: 100px; height: 20px; display: inline-block;"></div>			Comments on back?	

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
<b>2</b>	<b>CP</b>	<b>8828</b>	<b>EMF</b>	<b>229</b>	<b>0045</b>	<b>B1</b>			<b>LAUREL WEST T3</b>	<b>N</b>	<b>N</b>	<b>1</b>	<b>229D</b>
Description <b>Right side fuel cap disconnected.</b>													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <div style="border: 1px solid black; width: 20px; height: 20px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 20px; display: inline-block;"></div>			Date(mm/dd/yyyy): <div style="border: 1px solid black; width: 100px; height: 20px; display: inline-block;"></div>			Comments on back?	

**DEPARTMENT OF TRANSPORTATION**  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 127	Report Date 8/22/2023
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	CP	8828	EMF	229	0045	A4			LAUREL WEST T3	N	N	1	229D

**Description**

Right side locomotive I.D. decal damaged, not fully readable.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	CP	8828	EMF	229	0093	C1			LAUREL WEST T3	N	N	1	229D

**Description**

Right side emergency fuel shut off decal damaged, not fully readable.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	TTZX	863204	F	215	0301	A1			LAUREL WEST T3	N	N	1	215

**Description**

Right side car I.D. faded out & build date missing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	LW	879916	F	232	0103	F3			LAUREL WEST T3	N	N	1	232

**Description**

R-2 Brake shoe partly broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

**DEPARTMENT OF TRANSPORTATION**  
FEDERAL RAILROAD ADMINISTRATION (FRA)

# INSPECTION REPORT

(Continuation)

OMB Approval No.: 2130-0509

Inspector's ID No. M3003	Report No. 127	Report Date 8/22/2023
-----------------------------	-------------------	--------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	TTZX	861510	F	231	0120	B1			LAUREL WEST T3	N	N	1	231

Description  
Brake step bent / broken to the point it is unsafe for use.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	WRWK	29533	F						LAUREL WEST T3	N	N	0	

Description - [\*\* Comment to Railroad/Company \*\*]  
Right side "RIFD" tag broken.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9									LAUREL WEST T3	N	N	0	LTM

Description - [\*\* Comment to Railroad/Company \*\*]  
Meet with train crew to discuss best / safe inspection procedures for occupied train.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
-----------------------	---	-----------	------------

Written Notification to FRA of Remedial Action is:	<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
--	--	----------------------	-------------------	-------------------