

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name Voigt, Jordan				Inspector's Signature				Inspector's ID No. M3004		Report No. 17		Date		
												yy 2021	mm 01	dd 26
Railroad/Company Name & Address MONTANA RAIL LINK Missoula MT						R/C R		Division SYSTEM		RR/Co. Representative (Receipt Acknowledged) Name Matt Olson Title Mechanical Foreman Email Signature _____				
						RR/Co. Code MRL		Subdivision SYSTEM						
From: City MISSOULA				Codes 0830		Destination City & County				Codes		From Latitude		
State MT				30		City						From Longitude		
County MISSOULA				C063		County						To Latitude		
Mile Post: From				To		Inspection Point MISSOULA YARD						To Longitude		
Activity Code:	215	224	231	232	232X							CARS		
Units:	55	55	55	55	1							55		
Sub Units:	0	0	0	0	1							0		

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	GATX	101085	T	215	0103	FII				N	N	1	215

Description
 Shelled wheel (R2).

Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div>			Date(mm/dd/yyyy): <div style="border: 1px solid black; width: 80px; height: 15px; display: inline-block;"></div>			Comments on back?		

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	GATX	101102	T	215						N	N	0	

Description - [** Comment to Railroad/Company **]
 R2 bearing has a significant amount of grease around seal (no defect as there's not clearly formed droplets).

Seal Applied			Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No						Latitude:			Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional						Railroad Action Code <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div> <div style="border: 1px solid black; width: 20px; height: 15px; display: inline-block;"></div>			Date(mm/dd/yyyy): <div style="border: 1px solid black; width: 80px; height: 15px; display: inline-block;"></div>			Comments on back?		